

Alliance Rental Condition Report

Table of Contents

Introduction	2
Repairs & Servicing	2
Known Issues	2
Safety equipments	2
External Layout	3
Internal Layout	4
Caravan Accessories	4

Introduction

Welcome to your Rental Condition Report. This document records the current condition of your hired caravan before your rental begins. Just like when you hire a car, we document any existing marks, issues, or repairs to protect both parties.

This report shows:

- Current condition and any existing marks
- Recent history of repairs and maintenance
- Known issues
- Available accessories
- Safety features

Please review this document carefully before starting your hire and let us know if you notice anything that isn't listed here.

Repairs & Servicing

- 25 Jun 2024
 - Fit new tow electric
 - Fix curtain track
 - Replaced 12v plug
- 06 Jun 2024
 - Full annual service


Known Issues

- None


Safety equipments

- CO2 detector: Expires in 2028, battery last replaced on Wed, 20 Nov 2024.
- Smoke alarm detector: Expires in 2028, battery last replaced on Wed, 20 Nov 2024.
- Fire blanket: Fitted on 23 Aug 2022.

External Layout



Internal Layout



Caravan Accessories

- Water container
- Water hose
- Water container handle
- Grey waste container
- Twin connector
- Wheel jack
- Pink fluid
- Watering Can to pour pink fluid into toilet\
- Gas canister
- Manual leg lift
- Key safe
- Fire blanket
- Fire extinguisher
- Smoke alarm
- CO2 alarm
- Optionally, solar panel and second battery